STATE OF TEXAS WELL REPORT for Tracking #733411

Owner:	**Geddis Canyon Ranch**	Owner Well #:	**GCR COP W WW #2**
Address:	**PO Box 1408** **Pearsall, TX 78061**	Grid #:	**54-41-6**
Well Location:	**Hwy 349** **Dryden, TX**	Latitude:	**30° 18' 34.88" N**
	23 mi N of Dryden off of Hwy 349	Longitude:	**101° 54' 44.42" W**
Well County:	**Terrell**	Elevation:	**2462 ft. above sea level**

Type of Work: **New Well** Proposed Use: **Stock**

Drilling Start Date: **9/22/2026** Drilling End Date: **9/24/2026**

Borehole:

Diameter (in.)	*Top Depth (ft.)*	*Bottom Depth (ft.)*
13.5	**0**	**20**
10	**0**	**725**

Drilling Method: **Air Rotary**

Borehole Completion: **Straight Wall**

Annular Seal Data:

Top Depth (ft.)	*Bottom Depth (ft.)*	*Description (number of sacks & material)*
0	**20**	**Cement 8 Bags/Sacks**
400	**520**	**Bentonite 10 Bags/Sacks**

Seal Method: **Poured**

Sealed By: **Driller**

Distance to Property Line (ft.): **500+**

Distance to Septic Field or other concentrated contamination (ft.): **500+**

Distance to Septic Tank (ft.): **500+**

Method of Verification: **Visual**

Surface Completion: **Surface Sleeve Installed** **Surface Completion by Driller**

Water Level: **452 ft.** below land surface on **2026-09-25** Measurement Method: **Sonic/Radar**

Packers: **Rubber at 10 ft.**
Rubber at 520 ft.

Type of Pump: **Submersible**

Well Tests: **Jetted** **Yield: 10 GPM**

Water Quality:

Strata Depth (ft.)	Water Type
685 - 720	**Fresh**

Chemical Analysis Made: **No**

Did the driller knowingly penetrate any strata which contained injurious constituents?: **No**

Certification Data: The driller certified that the driller drilled this well (or the well was drilled under the driller's direct supervision) and that each and all of the statements herein are true and correct. The driller understood that failure to complete the required items will result in the report(s) being returned for completion and resubmittal.

Company Information: **Bull's Eye Services, LLC**

PO BOX 1408
PEARSALL, TX 78061

Driller Name: **Christopher M Rodgers** License Number: **59479**

Apprentice Name: **Derek A Aranda** Apprentice Number: **61702**

Comments: **No Data**

Lithology:
DESCRIPTION & COLOR OF FORMATION MATERIAL

Top (ft.)	Bottom (ft.)	Description
0	**3**	**TOPSOIL**
3	**65**	**TAN ROCK**
65	**185**	**CALICHE/LIMESTONE**
185	**225**	**WHITE LIMESTONE**
225	**245**	**BROWN LIMESTONE**
245	**425**	**WHITE LIMESTONE**
425	**505**	**GREY LIMESTONE**
505	**625**	**WHITE LIMESTONE**
625	**685**	**GREY LIMESTONE**
685	**710**	**COARSE GREY SAND/ROCK**
710	**725**	**GREY ROCK**

Casing:
BLANK PIPE & WELL SCREEN DATA

Dia (in.)	Type	Material	Sch./Gage	Top (ft.)	Bottom (ft.)
10.75	**Blank**	**New Steel**	**32#**	**0**	**20**
5	**Blank**	**New Plastic (PVC)**	**SDR 17**	**0**	**525**
5	**Screen**	**New Plastic (PVC)**	**SDR 17 0.032**	**525**	**725**

IMPORTANT NOTICE FOR PERSONS HAVING WELLS DRILLED CONCERNING CONFIDENTIALITY

TEX. OCC. CODE Title 12, Chapter 1901.251, authorizes the owner (owner or the person for whom the well was drilled) to keep information in Well Reports confidential. The Department shall hold the contents of the well log confidential and not a matter of public record if it receives, by certified mail, a written request to do so from the owner.

Please include the report's Tracking Number on your written request.

Texas Department of Licensing and Regulation
P.O. Box 12157
Austin, TX 78711
(512) 334-5540